## New Jersey Department of Transportation FY 2002 - 2003 Study and Development Program

ROUTE/PROGRAM	Project ID Numbers	
ROOTE/T ROOK/IIII	DB No.	TIP No.

280 Clifton Avenue to Route 21,
Drainage

93185 93185

#### LOCATION/DESCRIPTION

This identified drainage problem from Clifton Avenue to the vicinity of Route 21 results in periodic flooding during heavy rain. Conditions noted include antiquated drainage system; major traffic disruption.

SPONSOR: NJDOT COUNTY: Essex

MILEPOSTS: 13.40 - 14.50 STRUCTURE NO.: N/A

MPO	Phase	Year
NJTPA	FA	2002
NJTPA	FSD	2003

280 Downtown Connector, Phase III

824B

824B

### LOCATION/DESCRIPTION

Proposed Newark Downtown Connector, Phase III

This Proposed study will determine potentital alignment for Boulevard from First Street to Raymond Boulevard.

SPONSOR: NJDOT
COUNTY: Essex
MILEPOSTS: N/A
STRUCTURE NO.: N/A

МРО	Phase	Year
NJTPA	CD	2003

## New Jersey Department of Transportation FY 2002 - 2003 Study and Development Program

ROUTE/PROGRAM	Project ID Numbers	
ROOTE/TROOK/AW	DB No.	TIP No.

280 Passaic River Bridge (AKA Stickel Bridge)

00358

00358

#### LOCATION/DESCRIPTION

Proposed replacement of the bridge over the Passaic River

This vertical lift bridge is 626 feet long and carries six lanes of traffic. This structurally deficient and functionally obsolete structure is in overall poor condition with the deck ir serious condition. Since the Coast Guard has proposed to permanently close this bridge to navigational traffic, it may be reasonable to replace this structure with a fixed bridge as there has not been any reported openings during 1999.

SPONSOR: NJDOT COUNTY: Essex

MILEPOSTS: 14.42 - 14.60 STRUCTURE NO.: 0731161

МРО	Phase	Year
NJTPA	FA	2002
NJTPA	FA	2003

280 Ramp A&B to Route 21

00314

00314

#### LOCATION/DESCRIPTION

Ramps A and B, Route 21 northbound to I-280 eastbound), proposed bridge replaceme

The project will address the proposed replacement of this structure which is listed in serious condition due to the severe deterioration of concrete in the deck and pier columns. Out of the seven main spans, Spans 4 through 8 are in poor condition. The columns shear reinforcement ties were not design in accordance with current standards; this combined with concrete deterioration makes the bridge more vulnerable for failure.

SPONSOR: NJDOT COUNTY: Essex MILEPOSTS: 14.43

STRUCTURE NO.: 0731160

МРО	Phase	Year
NJTPA	FA	2002
NJTPA	FA	2003

# New Jersey Department of Transportation FY 2002 - 2003 Study and Development Program

ROUTE/PROGRAM	Project ID Numbers
	DB No. TIP No.

280 Whittingham Place/Kingsley Street

+ 98387

98387

#### LOCATION/DESCRIPTION

Proposed intersection improvements at the entrance ramp to I-280 East, Whittingham Place, and Kingsley Street

This proposed project will provide for improvements in the vicintiy of the entrance ramp to I-280 East, Whittingham Place, and Kingsley Street.

SPONSOR: NJDOT
COUNTY: Essex
MILEPOSTS: 10.10
STRUCTURE NO.: N/A

МРО	Phase	Year
NJTPA	FSD	2002